

MEMORANDUM

| | | | |
|-------------|-----------------------------|-----------------|-----------------------|
| TO | Dawn MacNeil, STPA | FILE NO. | S-1329-16 |
| FROM | Dianne Theriault | SHIFT: | 0730 to 1730 |
| TEL | (902) 539-3012 | CC: | Shawn Bernon, STPA |
| FAX | (902) 539-3381 | | Wilfred Kaiser, STPA |
| DATE | 26 th June, 2009 | | Terry Smith, ALL-TECH |
| | | STPA NO. | TP2-0184 |

**SUBJECT: 25th June, 2009 Real-time Air Monitoring Results
Sydney Tar Ponds Agency – Material Processing Facility
FINAL REPORT**

Attached is a summary of Real-time particulate (as PM₁₀) results for air monitoring performed on the 25th of June, 2009. Shaun Dove and Alison Giovannetti of ALL-TECH Environmental Services Cape Breton Limited (ALL-TECH) performed all air monitoring activities.

Weather conditions on the day of sampling:

- Mainly sunny
- Temperature: approximately 26°C
- Wind Direction: Southwest

Comments: *ALL-TECH was on-Site at 0730 hours and sampling began as soon as there was site activity. Air monitoring was performed during AECOM's construction activities..*

All downwind and upwind measurements of PM₁₀ were below the established Site Action Level for this parameter of 180 µg/m³.

All downwind and upwind measurements of Total Volatile Organic Compounds (TVOC) were below the established Site Action Level for this parameter of 0.66 ppm. Each measurement is the average of a 15 minute sample. A minimum of 2 samples were taken downwind and 1 sample upwind every hour. All measurements were found to be below the detection limit of the instrument. Levels above detection limit will be noted in the table below.

Due to operational criteria, during periods of precipitation (snow and rain) and high humidity, TVOC sampling is halted and resumes after the precipitation has ended.

This report has been prepared by Alison Giovannetti and reviewed by Dianne Theriault. If you have any questions regarding this report, please do not hesitate to contact the undersigned.

Sincerely,



Dianne Theriault, B.Tech
Environmental Technologist
ALL-TECH Environmental Services Cape Breton Ltd.

Copied via e-mail:

Shawn Bernon shawn@tarpondscleanup.ca, Wilfred Kaiser wilfred@tarpondscleanup.ca, Nancy LeDrew nancy@tarpondscleanup.ca, Trish Magliaro trish@tarpondscleanup.ca, Terry Smith tsmith@toalltech.com, Phyllis Low pilow@toalltech.com, Dianne Theriault dtheriault@toalltech.com, Darren Gardiner dgardiner@croworld.com, Darren Lawless dlawless@toalltech.com, Kevin Mac Pherson kevinmacp@cbcl.ca, Kathy Harquail kharquail@toalltech.com

Real-time Airborne PM₁₀ Concentration Results
Sydney Tar Ponds Agency – Material Processing Facility
25th June, 2009

| Sample No. & Air Monitoring Location | Time of Day | PM₁₀ Action Level (µg/m³) | Average Result (µg/m³) | Wind Direction | Relative Position | Description of Activity | Observations that may affect sample |
|--|--------------------|--|--|-----------------------|--------------------------|--------------------------------|---|
| 1 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 0800 | 180 | 6 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 2 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 0800 | 180 | 7 | Southwest | Downwind | Zoom boom operating | No observations seen to affect sampling integrity |
| 3 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 0840 | 180 | 9 | Southwest | Downwind | Zoom boom operating | No observations seen to affect sampling integrity |
| 4 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 0900 | 180 | 6 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 5 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 0900 | 180 | 11 | Southwest | Downwind | Zoom boom operating | No observations seen to affect sampling integrity |

| Sample No. & Air Monitoring Location | Time of Day | PM ₁₀ Action Level (µg/m ³) | Average Result (µg/m ³) | Wind Direction | Relative Position | Description of Activity | Observations that may affect sample |
|---|-------------|--|-------------------------------------|----------------|-------------------|------------------------------|---|
| 6 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 0925 | 180 | 8 | Southwest | Downwind | Zoom boom operating | No observations seen to affect sampling integrity |
| 7 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 1000 | 180 | 6 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 8 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1000 | 180 | 6 | Southwest | Downwind | No activity observed on site | No observations seen to affect sampling integrity |
| 9 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1020 | 180 | 8 | Southwest | Downwind | Excavator moving material | No observations seen to affect sampling integrity |
| 10 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 1100 | 180 | 7 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 11 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1100 | 180 | 8 | Southwest | Downwind | Excavator moving material | No observations seen to affect sampling integrity |

| Sample No. & Air Monitoring Location | Time of Day | PM ₁₀ Action Level (µg/m ³) | Average Result (µg/m ³) | Wind Direction | Relative Position | Description of Activity | Observations that may affect sample |
|---|-------------|--|-------------------------------------|----------------|-------------------|------------------------------|---|
| 12 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1140 | 180 | 9 | Southwest | Downwind | Excavator moving material | No observations seen to affect sampling integrity |
| 13 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 1200 | 180 | 10 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 14 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1200 | 180 | 9 | Southwest | Downwind | No activity observed on site | No observations seen to affect sampling integrity |
| 15 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1225 | 180 | 7 | Southwest | Downwind | No activity observed on site | No observations seen to affect sampling integrity |
| 16 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 1300 | 180 | 8 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 17 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1300 | 180 | 8 | Southwest | Downwind | Zoom boom operating | No observations seen to affect sampling integrity |

| Sample No. & Air Monitoring Location | Time of Day | PM ₁₀ Action Level (µg/m ³) | Average Result (µg/m ³) | Wind Direction | Relative Position | Description of Activity | Observations that may affect sample |
|---|-------------|--|-------------------------------------|----------------|-------------------|------------------------------|---|
| 18 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1320 | 180 | 11 | Southwest | Downwind | Excavator moving material | No observations seen to affect sampling integrity |
| 19 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 1400 | 180 | 10 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 20 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1400 | 180 | 12 | Southwest | Downwind | Excavator moving material | No observations seen to affect sampling integrity |
| 21 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1440 | 180 | 12 | Southwest | Downwind | Excavator moving material | No observations seen to affect sampling integrity |
| 22 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 1500 | 180 | 10 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 23 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1500 | 180 | 12 | Southwest | Downwind | No activity observed on site | No observations seen to affect sampling integrity |

| Sample No. & Air Monitoring Location | Time of Day | PM ₁₀ Action Level (µg/m ³) | Average Result (µg/m ³) | Wind Direction | Relative Position | Description of Activity | Observations that may affect sample |
|--|-------------|--|-------------------------------------|----------------|-------------------|------------------------------|---|
| 24 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1520 | 180 | 12 | Southwest | Downwind | Man-lift operating | No observations seen to affect sampling integrity |
| 25 75m South of Ferry St. and Railway Rd. intersection (N 46° 08.680' W 060° 11.476') | 1600 | 180 | 9 | Southwest | Upwind | Background | No observations seen to affect sampling integrity |
| 26 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1600 | 180 | 13 | Southwest | Downwind | Man-lift operating | No observations seen to affect sampling integrity |
| 27 60m Southeast of TP2 main entrance (N 46° 08.942' W 060° 11.266') | 1640 | 180 | 13 | Southwest | Downwind | No activity observed on site | No observations seen to affect sampling integrity |

Notes: Air sample duration for each monitoring event was 15 minutes.

Summary of Downwind PM₁₀ Action Levels

| Average PM ₁₀ Concentration (µg/m ³) | Averaging Period (Hours) | Downwind Action Level (µg/m ³) |
|---|--------------------------|--|
| 8 | 1 | 125 |
| 9 | 4 | 85 |
| 10 | 8 | 70 |

VOC Monitoring

| Monitoring Method | Yes | No |
|---------------------------|-----|----|
| Sustained Odours Observed | | • |
| P.I.D. Required | • | |