

MEMORANDUM

TO Dawn MacNeil, STPA
FROM Dianne Theriault
TEL (902) 539-3012
FAX (902) 539-3381
DATE 4th March, 2009

FILE NO. S-1279-01
SHIFT: 0730 to 1730
CC: Shawn Bernon, STPA
Wilfred Kaiser, STPA
Terry Smith, ALL-TECH
STPA NO. TP2-0117

**SUBJECT: 4th March, 2009, Real-time Air Monitoring Results
Sydney Tar Ponds Agency – Material Processing Facility
FINAL REPORT**

Attached is a summary of Real-time particulate (as PM₁₀) results for air monitoring performed on the 4th of March, 2009. Tyler Rowe and Shaun Dove, of ALL-TECH Environmental Services Cape Breton Limited (ALL-TECH), performed all air monitoring activities.

Weather conditions on the day of sampling:
- Mainly cloudy, sunny breaks
- Temperature: approximately -6°C
- Wind Direction: West

Comments: *ALL-TECH was on-Site at 0730 hours and sampling began as soon as there was site activity. Air monitoring was performed during AECOM's construction activities.*

All downwind and upwind measurements of PM₁₀ were below the established Site Action Level for this parameter of 155 µg/m³.

All downwind and upwind measurements of Total Volatile Organic Compounds (TVOC) were below the established Site Action Level for this parameter of 0.66 ppm. Each measurement is the average of a 15 minute sample. A minimum of 2 samples were taken downwind and 1 sample upwind every hour. All measurements were found to be below the detection limit of the instrument. Levels above detection limit will be noted in the table below.

Due to operational criteria, during periods of precipitation (snow and rain) and high humidity, TVOC sampling is halted and resumes after the precipitation has ended.

This report has been prepared by Tyler Rowe and reviewed by Dianne Theriault. If you have any questions regarding this report, please do not hesitate to contact the undersigned.

Sincerely,



Dianne Theriault, B.Tech
Environmental Technologist
ALL-TECH Environmental Services Cape Breton Ltd.

Copied via e-mail:

Shawn Bernon shawn@tarpondscleanup.ca, Wilfred Kaiser wilfred@tarpondscleanup.ca, Nancy LeDrew nancy@tarpondscleanup.ca, Trish Magliaro trish@tarpondscleanup.ca, Terry Smith tsmith@toalltech.com, Phyllis Low pilow@toalltech.com, Dianne Theriault dtheriault@toalltech.com, Darren Gardiner dgardiner@croworld.com, Darren Lawless dlawless@toalltech.com, Kevin Mac Pherson kevinmacp@cbcl.ca, Kathy Harquail kharquail@toalltech.com

Real-time Airborne PM₁₀ Concentration Results
Sydney Tar Ponds Agency – Material Processing Facility
4th March, 2009

Sample No. & Air Monitoring Location	Time of Day	PM₁₀ Action Level (µg/m³)	Average Result (µg/m³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
1 Railway property, 100m North of Ferry Street	0800	155	4	West	Upwind	Background	No observations seen to affect sampling integrity
2 Inglis Street, 50m North of Spar Road	0800	155	3	West	Downwind	No activity observed on site	No observations seen to affect sampling integrity
3 Inglis Street, 50m North of Spar Road	0825	155	2	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
4 Railway property, 100m North of Ferry Street	0900	155	4	West	Upwind	Background	No observations seen to affect sampling integrity
5 Inglis Street, 50m North of Spar Road	0900	155	15	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
6 Inglis Street, 50m North of Spar Road	0945	155	1	West	Downwind	Two booms operating	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM₁₀ Action Level (µg/m³)	Average Result (µg/m³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
7 Railway property, 100m North of Ferry Street	1000	155	11	West	Upwind	Background	No observations seen to affect sampling integrity
8 Inglis Street, 50m North of Spar Road	1000	155	5	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
9 Inglis Street, 50m North of Spar Road	1020	155	2	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
10 Railway property, 100m North of Ferry Street	1100	155	3	West	Upwind	Background	No observations seen to affect sampling integrity
11 Inglis Street, 50m North of Spar Road	1100	155	3	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
12 Inglis Street, 50m North of Spar Road	1130	155	1	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
13 Railway property, 100m North of Ferry Street	1200	155	2	West	Upwind	Background	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM₁₀ Action Level (µg/m³)	Average Result (µg/m³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
14 Inglis Street, 50m North of Spar Road	1200	155	1	West	Downwind	No activity observed on site	No observations seen to affect sampling integrity
15 Inglis Street, 50m North of Spar Road	1245	155	1	West	Downwind	No activity observed on site	No observations seen to affect sampling integrity
16 Railway property, 100m North of Ferry Street	1300	155	6	West	Upwind	Background	No observations seen to affect sampling integrity
17 Inglis Street, 50m North of Spar Road	1300	155	1	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
18 Inglis Street, 50m North of Spar Road	1315	155	1	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
19 Railway property, 100m North of Ferry Street	1400	155	4	West	Upwind	Background	No observations seen to affect sampling integrity
20 Inglis Street, 50m North of Spar Road	1400	155	1	West	Downwind	Two booms operating	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM ₁₀ Action Level (µg/m ³)	Average Result (µg/m ³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
21 Inglis Street, 50m North of Spar Road	1440	155	-1	West	Downwind	Two booms operating	Instrument recalibration required
22 Railway property, 100m North of Ferry Street	1500	155	3	West	Upwind	Background	No observations seen to affect sampling integrity
23 Inglis Street, 50m North of Spar Road	1500	155	3	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
24 Inglis Street, 50m North of Spar Road	1535	155	3	West	Downwind	Two booms operating	No observations seen to affect sampling integrity
25 Railway property, 100m North of Ferry Street	1600	155	3	West	Upwind	Background	No observations seen to affect sampling integrity
26 Inglis Street, 50m North of Spar Road	1600	155	3	West	Downwind	No activity observed on site	No observations seen to affect sampling integrity
27 Inglis Street, 50m North of Spar Road	1645	155	1	West	Downwind	No activity observed on site	No observations seen to affect sampling integrity

Notes: Air sample duration for each monitoring event was 15 minutes.

Comparison of Downwind Daily Results for Dust Budget

Location	Duration	Dust Budget Value ($\mu\text{g}/\text{m}^3$)	Dust Budget Exceedance Value ($\mu\text{g}/\text{m}^3$)
Inglis Street, 50m North of Spar Road	0800 to 0859	3	990
Inglis Street, 50m North of Spar Road	0900 to 0959	10	990
Inglis Street, 50m North of Spar Road	1000 to 1059	14	990
Inglis Street, 50m North of Spar Road	1100 to 1159	15	990
Inglis Street, 50m North of Spar Road	1200 to 1259	16	990
Inglis Street, 50m North of Spar Road	1300 to 1359	17	990
Inglis Street, 50m North of Spar Road	1400 to 1459	18	990
Inglis Street, 50m North of Spar Road	1500 to 1559	21	990
Inglis Street, 50m North of Spar Road	1600 to 1659	23	990

VOC Monitoring

Monitoring Method	Yes	No
Sustained Odours Observed		•
P.I.D. Required	•	