

MEMORANDUM

TO	Dawn MacNeil, STPA	FILE NO.	S-1291-18
FROM	Dianne Theriault	SHIFT:	0730 to 1730
TEL	(902) 539-3012	CC:	Shawn Bernon, STPA
FAX	(902) 539-3381		Wilfred Kaiser, STPA
DATE	28 th April, 2009		Terry Smith, ALL-TECH
		STPA NO.	TP2-0152

**SUBJECT: 27th April, 2009, Real-time Air Monitoring Results
Sydney Tar Ponds Agency – Material Processing Facility
FINAL REPORT**

Attached is a summary of Real-time particulate (as PM₁₀) results for air monitoring performed on the 27th of April, 2009. Shaun Dove and Alison Giovannetti, of ALL-TECH Environmental Services Cape Breton Limited (ALL-TECH), performed all air monitoring activities.

Weather conditions on the day of sampling:

- Mainly sunny
- Temperature: approximately 10°C
- Wind Direction: North

Comments: *ALL-TECH was on-Site at 0730 hours and sampling began as soon as there was site activity. Air monitoring was performed during AECOM's construction activities.*

All downwind and upwind measurements of PM₁₀ were below the established Site Action Level for this parameter of 155 µg/m³.

All downwind and upwind measurements of Total Volatile Organic Compounds (TVOC) were below the established Site Action Level for this parameter of 0.66 ppm. Each measurement is the average of a 15 minute sample. A minimum of 2 samples were taken downwind and 1 sample upwind every hour. All measurements were found to be below the detection limit of the instrument. Levels above detection limit will be noted in the table below.

Due to operational criteria, during periods of precipitation (snow and rain) and high humidity, TVOC sampling is halted and resumes after the precipitation has ended.

This report has been prepared by Alison Giovannetti and reviewed by Dianne Theriault. If you have any questions regarding this report, please do not hesitate to contact the undersigned.

Sincerely,



Dianne Theriault, B.Tech
Environmental Technologist
ALL-TECH Environmental Services Cape Breton Ltd.

Copied via e-mail:

Shawn Bernon shawn@tarpondscleanup.ca, Wilfred Kaiser wilfred@tarpondscleanup.ca, Nancy LeDrew nancy@tarpondscleanup.ca, Trish Magliaro trish@tarpondscleanup.ca, Terry Smith tsmith@toalltech.com, Phyllis Low pilow@toalltech.com, Dianne Theriault dtheriault@toalltech.com, Darren Gardiner dgardiner@croworld.com, Darren Lawless dlawless@toalltech.com, Kevin Mac Pherson kevinmacp@cbcl.ca, Kathy Harquail kharquail@toalltech.com

Real-time Airborne PM₁₀ Concentration Results
Sydney Tar Ponds Agency – Material Processing Facility
27th April, 2009

Sample No. & Air Monitoring Location	Time of Day	PM₁₀ Action Level (µg/m³)	Average Result (µg/m³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
1 350m North of Inglis St. and Spar Rd. intersection	0800	155	12	North	Upwind	Background	No observations seen to affect sampling integrity
2 20m Northwest of Inglis St. and Terminal Rd. intersection	0800	155	14	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
3 20m Northwest of Inglis St. and Terminal Rd. intersection	0830	155	11	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
4 350m North of Inglis St. and Spar Rd. intersection	0900	155	14	North	Upwind	Background	No observations seen to affect sampling integrity
5 20m Northwest of Inglis St. and Terminal Rd. intersection	0900	155	13	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
6 20m Northwest of Inglis St. and Terminal Rd. intersection	0920	155	25	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM₁₀ Action Level (µg/m³)	Average Result (µg/m³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
7 350m North of Inglis St. and Spar Rd. intersection	1000	155	14	North	Upwind	Background	No observations seen to affect sampling integrity
8 20m Northwest of Inglis St. and Terminal Rd. intersection	1000	155	13	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
9 20m Northwest of Inglis St. and Terminal Rd. intersection	1015	155	14	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
10 350m North of Inglis St. and Spar Rd. intersection	1100	155	8	North	Upwind	Background	No observations seen to affect sampling integrity
11 20m Northwest of Inglis St. and Terminal Rd. intersection	1100	155	9	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
12 20m Northwest of Inglis St. and Terminal Rd. intersection	1120	155	7	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
13 350m North of Inglis St. and Spar Rd. intersection	1200	155	11	North	Upwind	Background	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM ₁₀ Action Level (µg/m ³)	Average Result (µg/m ³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
14 20m Northwest of Inglis St. and Terminal Rd. intersection	1200	155	8	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
15 20m Northwest of Inglis St. and Terminal Rd. intersection	1215	155	7	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
16 350m North of Inglis St. and Spar Rd. intersection	1300	155	7	North	Upwind	Background	No observations seen to affect sampling integrity
17 20m Northwest of Inglis St. and Terminal Rd. intersection	1300	155	8	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
18 20m Northwest of Inglis St. and Terminal Rd. intersection	1320	155	9	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
19 350m North of Inglis St. and Spar Rd. intersection	1400	155	11	North	Upwind	Background	No observations seen to affect sampling integrity
20 20m Northwest of Inglis St. and Terminal Rd. intersection	1400	155	10	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM ₁₀ Action Level (µg/m ³)	Average Result (µg/m ³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
21 20m Northwest of Inglis St. and Terminal Rd. intersection	1445	155	12	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
22 350m North of Inglis St. and Spar Rd. intersection	1500	155	9	North	Upwind	Background	No observations seen to affect sampling integrity
23 20m Northwest of Inglis St. and Terminal Rd. intersection	1500	155	9	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
24 20m Northwest of Inglis St. and Terminal Rd. intersection	1530	155	9	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
25 350m North of Inglis St. and Spar Rd. intersection	1600	155	38	North	Upwind	Background	Trucks North of site driving down dirt road creating dust
26 20m Northwest of Inglis St. and Terminal Rd. intersection	1600	155	16	North	Downwind	Activity not visible from sampling location	No observations seen to affect sampling integrity
27 20m Northwest of Inglis St. and Terminal Rd. intersection	1645	155	11	North	Downwind	No activity observed on site	No observations seen to affect sampling integrity

Notes: Air sample duration for each monitoring event was 15 minutes.

Comparison of Downwind Daily Results for Dust Budget

Location	Duration	Dust Budget Value ($\mu\text{g}/\text{m}^3$)	Dust Budget Exceedance Value ($\mu\text{g}/\text{m}^3$)
20m Northwest of Inglis St. and Terminal Rd. intersection	0800 to 0859	13	990
20m Northwest of Inglis St. and Terminal Rd. intersection	0900 to 0959	32	990
20m Northwest of Inglis St. and Terminal Rd. intersection	1000 to 1059	46	990
20m Northwest of Inglis St. and Terminal Rd. intersection	1100 to 1159	54	990
20m Northwest of Inglis St. and Terminal Rd. intersection	1200 to 1259	62	990
20m Northwest of Inglis St. and Terminal Rd. intersection	1300 to 1359	71	990
20m Northwest of Inglis St. and Terminal Rd. intersection	1400 to 1459	82	990
20m Northwest of Inglis St. and Terminal Rd. intersection	1500 to 1559	91	990
20m Northwest of Inglis St. and Terminal Rd. intersection	1600 to 1659	105	990

VOC Monitoring

Monitoring Method	Yes	No
Sustained Odours Observed		•
P.I.D. Required	•	