

MEMORANDUM

TO	Dawn MacNeil, STPA	FILE NO.	S-1332-03
FROM	Dianne Theriault	SHIFT:	0630 to 1830
TEL	(902) 539-3012	CC:	Shawn Bernon, STPA Wilfred Kaiser, STPA Terry Smith, ALL-TECH
FAX	(902) 539-3381		
DATE	4 th June, 2009	STPA NO.	COCW-0046

**SUBJECT: 3rd June, 2009 Real-time Air Monitoring Results
Sydney Tar Ponds Agency – Vertical Cut-off Walls
FINAL REPORT**

Attached is a summary of Real-time particulate (as PM₁₀) results for air monitoring performed on the 3rd of June, 2009. Keith Neville and Dave Reeves of ALL-TECH Environmental Services Cape Breton Limited (ALL-TECH) performed all air monitoring activities.

Weather conditions on the day of sampling:

- Partly cloudy
- Temperature: approximately 19°C
- Wind Direction: Southwest to West to Southwest

Comments: *ALL-TECH was on-Site at 0630 hours and sampling began as soon as there was site activity. Air monitoring was performed during AECOM's construction activities.*

All downwind and upwind measurements of PM₁₀ were below the established Site Action Level for this parameter of 155 µg/m³.

All downwind and upwind measurements of Total Volatile Organic Compounds (TVOC) were below the established Site Action Level for this parameter of 0.66 ppm. Each measurement is the average of a 15 minute sample. A minimum of 2 samples were taken downwind and 1 sample upwind every hour. All measurements were found to be below the detection limit of the instrument. Levels above detection limit will be noted in the table below.

Due to operational criteria, during periods of precipitation (snow and rain) and high humidity, TVOC sampling is halted and resumes after the precipitation has ended.

This report has been prepared by Keith Neville and reviewed by Dianne Theriault. If you have any questions regarding this report, please do not hesitate to contact the undersigned.

Sincerely,



Dianne Theriault, B.Tech
Environmental Technologist
ALL-TECH Environmental Services Cape Breton Ltd.

Copied via e-mail:

Shawn Bernon shawn@tarpondscleanup.ca, Wilfred Kaiser wilfred@tarpondscleanup.ca, Nancy LeDrew nancy@tarpondscleanup.ca, Trish Magliaro trish@tarpondscleanup.ca, Terry Smith tsmith@toalltech.com, Phyllis Low pilow@toalltech.com, Dianne Theriault dtheriault@toalltech.com, Darren Gardiner dgardiner@croworld.com, Darren Lawless dlawless@toalltech.com, Kevin Mac Pherson kevinmacp@cbcl.ca, Kathy Harquail kharquail@toalltech.com

Real-time Airborne PM₁₀ Concentration Results
Sydney Tar Ponds Agency – Vertical Cut-off Walls
3rd June, 2009

Sample No. & Air Monitoring Location	Time of Day	PM ₁₀ Action Level (µg/m ³)	Average Result (µg/m ³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
1 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	0700	155	7	Southwest	Upwind	Background	No observations seen to affect sampling integrity
2 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	0700	155	8	Southwest	Downwind	No activity observed on site	No observations seen to affect sampling integrity
3 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	0720	155	22	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
4 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	0800	155	8	Southwest	Upwind	Background	No observations seen to affect sampling integrity
5 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	0800	155	12	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
6 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	0840	155	7	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM₁₀ Action Level (µg/m³)	Average Result (µg/m³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
7 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	0900	155	8	Southwest	Upwind	Background	No observations seen to affect sampling integrity
8 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	0900	155	6	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
9 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	0925	155	10	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
10 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	1000	155	6	Southwest	Upwind	Background	No observations seen to affect sampling integrity
11 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	1000	155	7	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
12 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	1030	155	5	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM ₁₀ Action Level (µg/m ³)	Average Result (µg/m ³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
13 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	1100	155	5	Southwest	Upwind	Background	No observations seen to affect sampling integrity
14 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	1100	155	11	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
15 30m North of coke ovens security trailer (N46°08.931') (W060°10.116')	1135	155	26	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
16 75m Northeast of Salvation Army (N46°08.761') (W060°10.556')	1200	155	5	West	Upwind	Background	No observations seen to affect sampling integrity
17 90m South of coke ovens security trailer (N46°08.924') (W060°10.107')	1200	155	6	West	Downwind	No activity observed on site	No observations seen to affect sampling integrity
18 90m South of coke ovens security trailer (N46°08.924') (W060°10.107')	1245	155	15	West	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM ₁₀ Action Level (µg/m ³)	Average Result (µg/m ³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
19 75m Northeast of Salvation Army (N46°08.761') (W060°10.556')	1300	155	5	West	Upwind	Background	No observations seen to affect sampling integrity
20 90m South of coke ovens security trailer (N46°08.924') (W060°10.107')	1300	155	7	West	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
21 90m South of coke ovens security trailer (N46°08.924') (W060°10.107')	1315	155	6	West	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
22 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	1400	155	4	Southwest	Upwind	Background	No observations seen to affect sampling integrity
23 25m Northeast of coke ovens security trailer (N46°08.925') (S060°10.115')	1400	155	17	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
24 25m Northeast of coke ovens security trailer (N46°08.925') (S060°10.115')	1440	155	11	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM ₁₀ Action Level (µg/m ³)	Average Result (µg/m ³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
25 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	1500	155	6	Southwest	Upwind	Background	No observations seen to affect sampling integrity
26 25m Northeast of coke ovens security trailer (N46°08.925') (S060°10.115')	1500	155	11	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
27 25m Northeast of coke ovens security trailer (N46°08.925') (S060°10.115')	1520	155	18	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
28 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	1600	155	7	Southwest	Upwind	Background	No observations seen to affect sampling integrity
29 25m Northeast of coke ovens security trailer (N46°08.925') (S060°10.115')	1600	155	10	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
30 25m Northeast of coke ovens security trailer (N46°08.925') (S060°10.115')	1615	155	9	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
31 50m Northeast of Salvation Army (N46°08.751') (W060°10.548')	1700	155	7	Southwest	Upwind	Background	No observations seen to affect sampling integrity

Sample No. & Air Monitoring Location	Time of Day	PM ₁₀ Action Level (µg/m ³)	Average Result (µg/m ³)	Wind Direction	Relative Position	Description of Activity	Observations that may affect sample
32 25m Northeast of coke ovens security trailer (N46°08.925') (S060°10.115')	1700	155	15	Southwest	Downwind	Excavators and dump trucks operating	No observations seen to affect sampling integrity
33 25m Northeast of coke ovens security trailer (N46°08.925') (S060°10.115')	1745	155	13	Southwest	Downwind	No activity observed on site	No observations seen to affect sampling integrity

Notes: Air sample duration for each monitoring event was 15 minutes.

Comparison of Downwind Daily Results for Dust Budget

Location	Duration	Dust Budget Value ($\mu\text{g}/\text{m}^3$)	Dust Budget Exceedance Value ($\mu\text{g}/\text{m}^3$)
30m North of coke of ovens security trailer	0700 to 0759	15	990
30m North of coke of ovens security trailer	0800 to 0859	25	990
30m North of coke of ovens security trailer	0900 to 0959	33	990
30m North of coke of ovens security trailer	1000 to 1059	39	990
30m North of coke of ovens security trailer	1100 to 1159	58	990
90m South of coke ovens security trailer	1200 to 1259	69	990
90m South of coke ovens security trailer	1300 to 1359	76	990
25m Northeast of coke ovens security trailer	1400 to 1459	90	990
25m Northeast of coke ovens security trailer	1500 to 1600	105	990
25m Northeast of coke ovens security trailer	1600 to 1659	115	990
25m Northeast of coke ovens security trailer	1700 to 1759	129	990

VOC Monitoring

Monitoring Method	Yes	No
Sustained Odours Observed		•
P.I.D. Required	•	